

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 07/05/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 06/28/12 – 0700, 07/12/12
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Larry Rader		Situation Unit Leader	Chicago, Illinois
8. Activity Log			
Time	Major Events		
11:00	<p>Operational status:</p> <ul style="list-style-type: none"> <li>• Source area pond: sheen observed.</li> <li>• Frac-City: observed crews cleaning boom in the decon pad.</li> <li>• Former Talmadge Creek dewatering pad location. Observed crew loading mats onto a truck at this location.</li> <li>• Confluence: no sheen observed.</li> <li>• Lily Pad area, no sheen observed.</li> <li>• South peninsula above Ceresco Dam: observed sheen on downstream side of peninsula. Sheen sweep boat was notified.</li> <li>• Sheen observed above Ceresco Dam. Sweep boat was observed operating in the area.</li> <li>• Ceresco Dam: sheen observed in southwest corner above dam and in river channel. Sheen sweep boat was notified.</li> <li>• Ceresco Dam: sheen and globules observed along the RDB, just upstream from the dam.</li> <li>• Ceresco Dam: sheen observed along the LDB along the southern wall of the dam.</li> <li>• MP6.5: group of kayakers observed.</li> <li>• Sheen sweep boat observed near MP 14.0.</li> <li>• South side of Mill Pond: no sheen observed. One sweeper boat observed near bridge.</li> <li>• MP 19.25 sediment trap: no sheen observed.</li> <li>• Sheen sweep boat operating near MP27.5.</li> <li>• Morrow Lake Delta: current configuration of E4 Boom System.</li> <li>• Crews inspecting the curtain along the E4 Boom System.</li> <li>• Morrow Lake Delta: Crews installing boom in southern of delta. Sheen observed in vicinity of boat.</li> <li>• Morrow Lake Delta: sheen observed along southern shore in vicinity of boats.</li> <li>• Morrow Lake: sheen sweep pontoon operating in northern portion of lake.</li> <li>• Fishing boat observed in northwestern corner of Morrow Lake.</li> <li>• Morrow Lake Dam: no sheen observed.</li> </ul>		
	Additional observations: None		
13:00	Return to ICP.		
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START			